



11090

SUPPORTS & STOPS

Tips

Eliminates workpiece chatter and vibration during machining.

Easy to actuate; locate and fix beneath workpiece, turn actuation handle and sprung loaded support will come into

contact with workpiece. Lock handle to set support.

Order No.	Support height	w_1	d_1	l_1	l_2
11090.W0060	28	45	6	56	20

